



## GREEN ENERGY INTERNATIONAL LIMITED

**LEKOIL NIGERIA LIMITED** 



# ACEBEACON GLOBAL ENERGY LIMITED CONRACTOR

#### **PROJECT COMPLETION REPORTS**

**FOR** 

ENGINEERING, PROCUREMENT, CONSTRUCTION, INSTALLATION AND COMMISSIONING OF LPG
PLANT PERIMETER LIGHTING, EARTHING SYSTEM AND LIGHTNING PROTECTION SYSTEM AT
OTAKIKPO MARGINAL FIELD, ANDONI, RIVERS STATE.

AND

PROCUREMENT, SUPPLY, AND INSTALLATION OF TEMPORARY (SOLAR LIGHT) PERIMETER LIGHTING SYSTEM AT OTAKIKPO MARGINAL FIELD, ANDONI, RIVERS STATE.

**07 SEPTEMBER, 2022** 





# GREEN ENERGY INTERNATIONAL LIMITED

**LEKOIL NIGERIA LIMITED** 



# ACEBEACON GLOBAL ENERGY LIMITED CONRACTOR

SUPPLY AND INSTALLATION OF SOLAR & MAIN PERIMETER LIGHTING AT OTAKIKPO MARGINAL FIELD, ANDONI, RIVERS STATE.

PROJECT COMPLETION REPORT

**GEIL-LEK-AGEL-PJM-RPT-001** 

20 JULY 2022





Contract No:

LEKOIL

Rev: A1

WORK COMPLETION REPORT

Page: 2 of 15

#### **ABBREVIATIONS**

AGEL ACEBEACON GLOBAL ENERGY LIMITED

GEIL GREEN ENERGY INTERNATIONAL LIMITED

#### **DEFINITIONS**

COMPANY GREEN ENERGY INTERNATIONAL LIMITED / LEKOIL NIGERIA LIMITED

CONTRACTOR ACEBEACON GLOBAL ENERGY LIMITED





Contract No:



Rev: A1

**Document Title:** 

#### WORK COMPLETION REPORT

**Page:** 3 of 15

#### **TABLE OF CONTENT**

1 INTRODUCTION	4
1 INTRODUCTION ····································	
1.1 Project Background · · · · · · · · · · · · · · · · · · ·	1
1.2 Scope of Work · · · · · · · · · · · · · · · · · · ·	1
1.3 Report Description · · · · · · · · · · · · · · · · · · ·	4
2 OTAKIKPO LPG FACILITY LIGHTING PHILOSOPHY	5
2.1 MAIN LIGHTING ······ 5	5
2.2 TEMPORARY/BACK-UP LIGHTING	5
3 EQUIPMENT SPECIFICATIONS	õ
3.1 Solar Light fitting ····································	õ
3.2 Main light fitting · · · · · · · · · · · · · · · · · · ·	3
3.3 LIGHTING CONTROL PANEL ····································	3
3.4 Junction Box · · · · · · · · · · · · · · · · · · ·	3
4 TEST RESULTS7	7
5 PICTURES	3
6 COMPLETION STATEMENT	3
7 APPENDIX	5
7.1 As-Built Drawings 15	5





Contract No:

LEKOIL

Rev: A1

Document Title:

WORK COMPLETION REPORT

**Page:** 4 of 15

#### 1 INTRODUCTION

#### 1.1 Project Background

The Otakikpo LPG Extraction plant project is targeted at removing LPG, Propane & Condensate Products from rich associated gas of Otakikpo Marginal field.

To achieve this project, hence the need for the provision of solar and main perimeter lighting for the entire Otakikpo LPG Extraction plant facility.

#### 1.2 Scope of Work

The scope of this project covers the procurement, construction, installation and commissioning of 41 nos. solar light fittings mounted on 41 nos. poles and 127 nos. main light fittings mounted on 41 nos. poles for the entire Otakikpo LPG Extraction plant facility.

The following components were supplied and installed to achieve the above setup:

- 1. 6m high galvanized flight poles
- 2. Solar light fittings
- 3. Ex-de Light fittings
- 4. Ex-de Junction boxes
- 5. Lighting control panel

#### 1.3 Report Description

This Document reports the work done in procurement, construction, installation and commissioning of pole-mounted solar and main light fittings at Otakikpo LPG Extraction plant facility.





Contract No:

LEKOIL

Rev: A1

Document Title:

WORK COMPLETION REPORT

**Page:** 5 of 15

#### 2 OTAKIKPO LPG FACILITY LIGHTING PHILOSOPHY

#### 2.1 Solar lighting

Temporary lighting with solar is a great alternative to main lighting for many applications, providing perimeter lighting with an even light spread, without the glare, noise, fumes, ongoing fuel costs and maintenance.

The solar-powered perimeter lights at Otakikpo LPG have a fully automatic operation and zero local emissions. During daylight hours solar energy is collected and stored in the batteries. In low light or night-time, the LED light activates automatically. The illumination also increases to 100% when movement is detected within 10m of the light. Once the movement has stopped, after a few minutes the light will dim to 40%. This means that the solar light will only work when needed them to, and hence no need to manually turn lamp off and on.

#### 2.2 Main Lighting

Perimeter security lighting is a vital part of an overall layered security plan. The benefits of lighting are many, but for security lighting system, it must deliver as a minimum the following: Provide a clear view of an area for the purpose of work, allowing movement to be easily detected, deny potential hiding places along frequently traveled foot routes, allow for facial recognition with electronic monitoring systems and on-site security personnel and deter crime against persons and property.

The perimeter main light at Otakikpo consist of 127 nos pole mounted 300kW explosion-proof LED flood lights. The lighting control automatically by the photocell which activated in low light or night-time. The Ex-de lighting panel consists of 7 nos 3pole outgoing circuits and protected by control circuit breakers.





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 6 of 15

### **3 EQUIPMENT SPECIFICATIONS**

### 3.1 Solar Light fitting

a	Ingress Protection rating	IP65
b	Battery Charge time	6-7 hours (Approx.)
С	Discharge Time	Over 12 hours
d	Lighting area	15 meters approx.
е	Unit lifespan	30,000 hours
f	Beam angle	120^60
g	Luminous Efficiency	110LN/W



### 3.2 Main light fitting

а	Manufacturer	Harvells-EX Atex
b	Туре	Explosion-proof LED light
С	Power	300W
d	Input	AC85-265V, 50Hz
е	ССТ	6000-7000K
f	Ingress Protection rating	IP67



### 3.3 Lighting Control Panel

а	IP Rating	IP66	
	Group, category, type of	Ex II 2 GD Ex d IIC T6, T5, T4, T3	
	protection, temperature	Gb Ex tb IIIC T85 °C, T100 °C,	
b	class	T135 °C, T200 °C Db	
С	Enclosures	AISI 316L (1.4404) stainless steel	
d	Conformity	EN 60529	
е	System voltage	400V AC	
е	Controls	Breakers, Contactors & Photocell	



#### 3.4 Junction box

а	IP Rating	IP66
b	Material	Aluminium Die Cast
С	Feature	Flameproof, Weatherproof
d	Туре	3 Way
е	Gas Group	IIA, IIB, Ex-d
f	Shape	Rectangular







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 7 of 15

#### 4 TEST RESULTS

S/N	Test	Result	
1	Continuity Test	Confirmed OK	
2	Insulation Resistance	Avg. 5 GΩ @ 1000VDC	
3	Photocell By-pass	Available	
4	Perimeter Lighting Photocell Functionality	Confirmed OK	
5	Earth Leakages on Poles and Junction boxes	No earth leakages	
6	Solar Lighting Photocell Functionality	Confirmed OK	
7	Power to the Lighting Panel and Junction boxes.	Confirmed OK	
8	Line to Line voltages to Lighting Panel and all Junction boxes	400V	
9	Line to neutral voltages to lighting fittings	230V	
10	Functionality of all Perimeter/Solar Lighting Fittings	Confirmed OK	





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 8 of 15

#### **PICTURES** 5





Fig 4.3: Prepared pole pedestal



Fig 4.2: Casting of light pole base



Fig 4.4: Light fittings prepared and terminated





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 9 of 15



Fig 4.5: Erected light pole





Fig 4.7: Erection of light pole with solar and main light fittings



Fig 4.8: Casting of Cable slab





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 10 of 15



Fig 4.9: Excavation of cable route



Fig 4.10: Pipes for cable road crossing



Fig 4.11: Re-Painting of light poles



Fig 4.12: Casting of cable marker





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 11 of 15



Fig 4.13: Laying of cable slab on cable way



Fig 4.14: Termination of cabled in lighting JB



Fig 4.15: Light cables in cable tray and extra protection for JB



Fig 4.16: Insulation resistance testing of cables





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 12 of 15



Fig 4.17: Testing of lighing panel

Fig 4.18: Connected lighting panel



Fig 4.19: Solar lighting illumination




Fig 4.20: Solar lighting illumination





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 13 of 15



Fig 4.21: Daylight testing of Perimeter light

Fig 4.22: Main lighting illumination





Contract No:

LEKOIL

Rev: A1

Document Title:

WORK COMPLETION REPORT

Page: 14 of 15

#### COMPLETION STATEMENT

This Project has been tested and confirmed to be sufficient for the purpose it was designed for. We hereby report this project as commissioned.

detonedin 22/07/2022

Engr. Ohore Utomeno Timipre

Electrical Project Engineer

ACEBEACON GLOBAL ENERGY LIMITED

1 22/07/2022 Sign

Name: Anackuse Mathan. I

Designation: Electrical Lead

GREEN ENERGY INTERNATIONAL LIMITED

Name: Vitus Ugm Designation: Proj. Engr (ESI)

LEKOIL NIGERIA LIMITED





Contract No:

LEKOIL


Rev: A1


WORK COMPLETION REPORT


**Page:** 15 of 15


#### 7 APPENDIX


### 7.1 As-Built Drawings





















# GREEN ENERGY INTERNATIONAL LIMITED

**LEKOIL NIGERIA LIMITED** 



# ACEBEACON GLOBAL ENERGY LIMITED CONRACTOR

SUPPLY AND INSTALLATION OF LIGHTNING PROTECTION SYSTEM AT OTAKIKPO MARGINAL FIELD, ANDONI, RIVERS STATE.

PROJECT COMPLETION REPORT

**GEIL-LEK-AGEL-PJM-RPT-002** 

20 JULY 2022





Contract No:

LEKOIL

Rev: A1

WORK COMPLETION REPORT

Page: 2 of 15

#### **ABBREVIATIONS**

AGEL ACEBEACON GLOBAL ENERGY LIMITED

GEIL GREEN ENERGY INTERNATIONAL LIMITED

#### **DEFINITIONS**

COMPANY GREEN ENERGY INTERNATIONAL LIMITED / LEKOIL NIGERIA LIMITED

CONTRACTOR ACEBEACON GLOBAL ENERGY LIMITED





Contract No:

LEKOIL

Rev: A1

### Document Title: WORK COMPLETION REPORT

**Page:** 3 of 15

1 INTRODUCTION ————————————————————————————————————
1.1 Project Background ————————————————————————————————————
1.2 Scope of Work
1.3 REPORT DESCRIPTION · · · · · · 4
2 LIGHTNING PROTECTION EQUIPMENT5
2.1 LIGHTNING ARRESTOR · · · · · · · · · · · · · · · · · · ·
2.2 PREVECTRON 3® S60 STANDARD COMPLIANCE AND TECHNICAL VALIDATION
3 EQUIPMENT SPECIFICATIONS
3.1 LIGHTNING ARRESTOR ····································
3.2 Bare Copper Tape 6
3.3 Inspection pit chamber ····································
3.4 Earth rod7
3.5 EARTH RESISTANCE TESTER ····································
4 TEST RESULTS8
4.1 LIGHTNING MAST 001 8
4.2 LIGHTNING MAST 002 ······ 8
4.3 LIGHTNING MAST 003 8
5 LIGHTNING ARRESTOR MONITORING
5.1 LOGIN INFORMATION ······9
5.2 REMOTELY MONITORED PARAMETERS9
5.3 Monitoring Interface ·····9
5.4 TEST PARAMETERS10
6 PICTURES
7 COMPLETION STATEMENT ····································
8 APPENDIX
8.1 As-Built Layout Drawings ······ 15
8.2 INDELEC ARRESTORS CERTIFICATES15





Contract No:

LEKOIL

Rev: A1

Document Title: WORK COMPLETION REPORT

**Page:** 4 of 15

#### 1 INTRODUCTION

#### 1.1 Project Background

The Otakikpo LPG Extraction plant project is targeted at removing LPG, Propane & Condensate Products from rich associated gas of Otakikpo Marginal field.

To achieve this project, hence the need for the mast-mounted plant wide lightning protection system for the entire Otakikpo LPG Extraction plant facility.

#### 1.2 Scope of Work

The scope of this project covers the construction, installation and commissioning of a mastmounted plant wide lightning protection system for the entire Otakikpo LPG Extraction plant facility.

The following components below were supplied and installed to achieve the above setup:

- 1. 30m high mast fit with guyed wires.
- 2. Lightning Arrestors
- 3. Copper earth rods, earth mats, chambers and accessories
- 4. Bare copper tapes
- 5. Earth cables

#### 1.3 Report Description

This Document reports the work done in construction, installation and commissioning of 3nos mast-mounted lightning protection system at Otakikpo LPG Extraction plant facility





Contract No:

LEKOIL

Rev: A1

Document Title: WORK COMPLETION REPORT

**Page:** 5 of 15

#### 2 LIGHTNING PROTECTION EQUIPMENT

#### 2.1 Lightning Arrestor

A lightning arrestor (also called lightning isolator) is a device used on electric power transmission and telecommunication systems to protect the insulation and conductors of the system from the damaging effects of lightning. The typical lightning arrester has a high-voltage terminal and a ground terminal. When a lightning surge (or switching surge, which is very similar) travels along the power line to the arrestor, the current from the surge is diverted through the arrestor, in most cases to earth.

If protection fails or is absent, lightning that strikes the electrical system introduces thousands of kilovolts that may damage the transmission lines, and can also cause severe damage to transformers and other electrical or electronic devices. Lightning-produced extreme voltage spikes in incoming power lines can damage electrical home appliances or even cause death.

#### 2.2 PREVECTRON 3® S60 Standard Compliance and Technical Validation

Lightning is a natural phenomenon. Lightning air terminals are exposed to a very large range of events: extreme climatic conditions (temperatures, humidiy etc), high intensity electrical shocks up to several hundreds of thousands of Amperes and unpredictable lightning frequency.

Lightning Protection standards such as NF-C 17-102, UNE 21 186 or NP4426 include detailed testing procedures that covers such extraordinary tough conditions. The PREVECTRON  $3^{\circ}$  Connect successfully passed these series of tests. Its integrated Lightning Counter was also tested according to the IEC 62 561 – 6 Edition 2 standard, confirming its full compliance to all relevant standards in the industry.

Lastly, the IoT connected system requires specific attention to work in severe electromagnetic lightning conditions and meet the CE marking requirements. INDELEC develops dedicated testing processes, both in the LiRi Lab and in real lightning conditions, to confirm the PREVECTRON 3® Connect compatibility in such environment.





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 6 of 15

### **3 EQUIPMENT SPECIFICATIONS**

### 3.1 Lightning Arrestor

а	Manufacturer	Indelec	
b	Model	PREVECTRON3® S60 EARLY STREAMER EMISSION AIR TERMINAL (ESE)	
С	Power Supply	High Performance LiFePo4 Battery	1
d	Operating Temperature range	-15°C to + 55°C	p)
е	Ingress Protection	IP 54	
f	Lightning current withstanding test (10/350μs)	limp 100kA (normative test)	
g	Max. current withstanding test	Imax 230 kA (Unicamp)	
h	Quantity installed	3	

### 3.2 Bare Copper Tape

а	Manufacturer	Furse	
b	Material	Copper	135
С	Model	TC030	
d	Dimension (mm)	25x3	133
е	Copper Weight Per Metre	0.67 kg	

### 3.3 Inspection pit chamber

а	Manufacturer	Furse	12/10/10
b	Model No.	PT205	
С	Material	Polymer	
d	Description	Lockable High Performance Poly	
е	Accessories	6 mm Allen key	





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 7 of 15

#### 3.4 Earth rod

а	Manufacturer	Furse	
b	Material	Copper	
С	Unit length	1.8m	
d	Interconnection method	Copper coupler	
е	Terminal type	Threaded	
f	Percentage of copper	100%	

#### 3.5 Earth Resistance Tester

а	Manufacturer	Megger	
b	Model	DET3TD	28
С	Test method	3Points	
d	Resistance accuracy	2% ±3 digits	
е	Calibration status	Valid	







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

**WORK COMPLETION REPORT** 

**Page:** 8 of 15

#### 4 TEST RESULTS

#### 4.1 Lightning Mast 001

Arrestor Serial number: P1543014345 Module Serial number: P1587000880

Location Description: Near Heavy Hydrocarbon Separation Unit

Test	Result
Earth Pit Test 1	$0.22\Omega$
Earth Pit Test 2	0.22Ω
Average	$0.22\Omega$



#### 4.2 Lightning Mast 002

Arrestor Serial number: P1543014088

Module Serial number: P1587000900

Location Description: Near Power Plant

Test	Result
Earth Pit Test 1	$0.17\Omega$
Earth Pit Test 2	0.30Ω
Average	$0.23\Omega$



#### 4.3 Lightning Mast 003

Arrestor Serial number: P1543014091 Module Serial number: P1587000903

Location Description: Near Loading Gantry

Test	Result
Earth Pit Test 1	0.27Ω
Earth Pit Test 2	0.37Ω
Average	0.32Ω







Contract No:



Rev: A1

Document Title:

WORK COMPLETION REPORT

**Page:** 9 of 15

#### 5 LIGHTNING ARRESTOR MONITORING

The lightning arrestor communicates its information to the user on a dedicated and secured web portal.

#### 5.1 Login Information

Link: https://bo.indelec-connect.com

Username: \*\*\*\*\*\*\*\*\*\*\*\*

Password: \*\*\*\*\*\*\*\*\*\*\*\*

Note: Username and Password has been provided to client.


#### **5.2** Remotely Monitored Parameters

The following are information monitored by the Prevectron®3 Connect program.

- Strike counter
- ESE Lightning rod test status
- Battery level
- GSM signal quality

#### 5.3 Monitoring Interface

Below is a representation of the different parameters as shown in the monitoring interface.







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 10 of 15

#### 5.4 **Test Parameters**

The left hand side symbols shows that the test status is faulty and needs some intervention whereas the right hand side symbols shows that the test status is okay and all is functioning well.



Date de l'évènement Date of the event



Initialisation Initialization



Etat du paratonnerre Prevectron3® Connect Prevectron3® Connect Status





Qualité du signal Signal quality





Niveau de charge batterie Battery charge



Nombre de coups de foudre Lightning discharges number





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 11 of 15

#### 6 PICTURES





Fig 4.3: PREVECTRON3® S60 ESE connected to mast member



Fig 4.2: Mast erection in progress



Fig 4.4: Base for guyed wire





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 12 of 15



Fig 4.5: Copper earth mat installation



Fig 4.6: Earth rod installation



Fig 4.7: Earth rod outlet in chamber



Fig 4.8: Megger earth test machine





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 13 of 15



Fig 4.9: Earth resistance test ongoing



Fig 4.10: Aviation light on top of mast



Fig 4.11: Mast guyed wires



Fig 4.12: Completed mast erection





Contract No:

**LEKOIL** 

Rev: A1

Document Title:

WORK COMPLETION REPORT

Page: 14 of 15

#### COMPLETION STATEMENT 7

This Project has been tested and confirmed to be sufficient for the purpose it was designed for. We hereby report this project as commissioned.

Womestine 22/07/22

Engr. Ohore Utomeno Timipre

Electrical Project Engineer

ACEBEACON GLOBAL ENERGY LIMITED

Name: Anarkwe Nathan I.

Designation:

GREEN ENERGY INTERNATIONAL LIMITED

Name: Vitus Ugm
Designation: Proj. Engr. (E&I)

LEKOIL NIGERIA LIMITED





Contract No:

LEKOIL


Rev: A1


**Document Title:** 


WORK COMPLETION REPORT


**Page:** 15 of 15


- 8 APPENDIX
- 8.1 As-Built Layout Drawings
- 8.2 Indelec Arrestors Certificates
















Modèle

Numéro de Série

PREVECTRON® 3 S 60

P1543014088

CERTIFICAT DE TEST, DE GARANTIE ET DE CONFORMITE A LA NORME NF C17-102 : 2011 POUR LES PARATONNERRES A DISPOSITIF D'AMORCAGE PREVECTRON 3®







Garant: INDELEC SA - 61 Chemin des Postes - 59500 DOUAI - FRANCE

France par INDELEC SA Attention: Ce certificat de garantie s'applique seulement aux paratonnerres à dispositif d'amorçage Prevectron 3® conçus et fabriqués en



Modèle

Numéro de Série

PREVECTRON® 3 S 60

P1543014091

CERTIFICAT DE TEST, DE GARANTIE ET DE CONFORMITE A LA NORME NF C17-102 : 2011 POUR LES PARATONNERRES A DISPOSITIF D'AMORCAGE PREVECTRON 3®







Garant: INDELEC SA - 61 Chemin des Postes - 59500 DOUAI - FRANCE

France par INDELEC SA Attention: Ce certificat de garantie s'applique seulement aux paratonnerres à dispositif d'amorçage Prevectron 3® conçus et fabriqués en



Modèle

Numéro de Série

PREVECTRON® 3 S 60

P1543014345

CERTIFICAT DE TEST, DE GARANTIE ET DE CONFORMITE A LA NORME NF C17-102 : 2011 POUR LES PARATONNERRES A DISPOSITIF D'AMORCAGE PREVECTRON 3®







Garant: INDELEC SA - 61 Chemin des Postes - 59500 DOUAI - FRANCE

France par INDELEC SA Attention: Ce certificat de garantie s'applique seulement aux paratonnerres à dispositif d'amorçage Prevectron 3® conçus et fabriqués en





# GREEN ENERGY INTERNATIONAL LIMITED

**LEKOIL NIGERIA LIMITED** 



# ACEBEACON GLOBAL ENERGY LIMITED CONRACTOR

SUPPLY AND INSTALLATION OF EARTHING PROTECTION SYSTEM AT OTAKIKPO MARGINAL FIELD, ANDONI, RIVERS STATE.

PROJECT COMPLETION REPORT

**GEIL-LEK-AGEL-PJM-RPT-003** 

**04 SEPTEMBER 2022** 





Contract No:

LEKOIL

Rev: A1

WORK COMPLETION REPORT

**Page:** 2 of 15

## **ABBREVIATIONS**

AGEL ACEBEACON GLOBAL ENERGY LIMITED

GEIL GREEN ENERGY INTERNATIONAL LIMITED

# **DEFINITIONS**

COMPANY GREEN ENERGY INTERNATIONAL LIMITED / LEKOIL NIGERIA LIMITED

CONTRACTOR ACEBEACON GLOBAL ENERGY LIMITED



**Document Title:** 



#### Contract No:

LEKOIL

Rev: A1

# WORK COMPLETION REPORT

**Page:** 3 of 15

1 INTRODUCTION ····································
1.1 Project Background ······· 4
1.2 Scope of Work ······4
1.3 Report Description · · · · · · · · · · · · · · · · · · ·
2 EARTHING PROTECTION SYSTEM
2.1 GENERAL 5
2.2 Purposes of Earthing ······· 5
3 EQUIPMENT SPECIFICATIONS 6
3.1 Earth Enhancement Mix
3.1 EARTH ENHANCEMENT MIX
3.2 INSPECTION PIT CHAMBER
3.4 EARTH ROD  3.4 EARTH RESISTANCE TESTER6
4 TEST RESULTS7
5 PICTURES9
6 COMPLETION STATEMENT · · · · · · · · · · · · · · · · · · ·
7 APPENDIX ····································
7.1 As-Built Layout Drawings ········15



**Document Title:** 



Contract No:

LEKOIL

Rev: A1

WORK COMPLETION REPORT

**Page:** 4 of 15

#### 1 INTRODUCTION

# 1.1 Project Background

The Otakikpo LPG Extraction plant project is targeted at removing LPG, Propane & Condensate Products from rich associated gas of Otakikpo Marginal field.

To achieve this project, hence the need for the mast-mounted plant wide lightning protection system for the entire Otakikpo LPG Extraction plant facility.

# 1.2 Scope of Work

The scope of this project covers the construction, installation and commissioning of earthing protection systems for the entire Otakikpo LPG Extraction plant facility.

The following components were supplied and installed to achieve the above setup:

- 1. Copper earth rods, earth mats, chambers and accessories
- 2. Earth enhancement chemical
- 3. Earth cables

## 1.3 Report Description

This Document reports the work done in construction, installation and commissioning of 60nos. earth pits fully bonded and earthing of 41nos light poles and lighting control panel Otakikpo LPG Extraction plant facility.



**Document Title:** 



Contract No:

LEKOIL

Rev: A1

WORK COMPLETION REPORT

**Page:** 5 of 15

#### 2 EARTHING PROTECTION SYSTEM

#### 2.1 General

An earthing system connects specific parts of an electric power system with the ground, typically the Earth's conductive surface, for safety and functional purposes. The choice of earthing system can affect the safety and electromagnetic compatibility of the installation. Regulations for earthing systems vary considerably among countries, though most follow the recommendations of the International Electrotechnical Commission (IEC). Regulations may identify special cases for earthing in mines, in patient care areas, or in hazardous areas of industrial plants.

## 2.2 Purposes of Earthing

There are three main purposes for earthing:

#### **System earthing**

System earthing serves a purpose of electrical safety throughout the system that is not caused by an electrical fault. Its main purpose is to prevent static buildup and to protect against power surges caused by nearby lightning strikes or switching. Static buildup, as induced by friction for example, such as when wind blows onto a radio mast, is dissipated to the Earth. In the event of a surge, a lightning arrester, a surge arrester or a SPD will divert the excess current to the Earth before it reaches an appliance.

System earthing also allows for equipotential bonding to all metalworks to prevent potential differences between them. Having Earth as a common reference point also keeps the electrical system's potential difference limited to the supply voltage.

#### **Equipment earthing**

Equipment earthing serves a purpose of electrical safety in an electrical fault. Its main purpose is to prevent equipment damage and the risk of an electric shock. This type of earthing is not an earth connection, technically speaking. When current flows from a line conductor to an earth wire, as is the case when a line conductor makes contact with an earthed surface in a Class I appliance, an automatic disconnection of supply (ADS) device such as a circuit breaker or a RCD will automatically open the circuit to clear the fault.

#### **Functional earthing**

Functional earthing serves a purpose other than electrical safety. Example purposes include electromagnetic interference (EMI) filtering in an EMI filter, and the use of the Earth as a return path in a single-wire earth return distribution system.





Contract No:



Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 6 of 15

# **3 EQUIPMENT SPECIFICATIONS**

## 3.1 Earth Enhancement Mix

a	Product	Marconite
b	Packaging size	25kg
С	Packaging type	bag
d	Physical state	Powder



# 3.2 Inspection pit chamber

а	Manufacturer	Furse
b	Model No.	PT205
С	Material	Polymer
d	Description	Lockable High Performance Poly
е	Accessories	6 mm Allen key



# 3.3 Earth rod

а	Manufacturer	Furse	
b	Material	Copper	
С	Unit length	1.8m	
d	Interconnection method	Copper coupler	
е	Terminal type	Threaded	
f	Percentage of copper	100%	

# 3.4 Earth Resistance Tester

	а	Manufacturer	Megger	
	b	Model	DET3TD	269
Ī	С	Test method	3Points	-
	d	Resistance accuracy	2% ±3 digits	-0
	е	Calibration status	Valid	





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 7 of 15

# 4 TEST RESULTS

	Results				
Pit Tag	Individual ( $\Omega$ )	Bonded ( $\Omega$ )			
Earth Pit 1	0.52	0.42			
Earth Pit 2	0.63	0.37			
Earth Pit 3	0.47	0.25			
Earth Pit 4	0.51	0.60			
Earth Pit 5	0.55	0.75			
Earth Pit 6	0.67	0.12			
Earth Pit 7	0.49	0.32			
Earth Pit 8	0.71	0.32			
Earth Pit 9	0.66	0.25			
Earth Pit 10	0.54	0.29			
Earth Pit 11	0.69	0.32			
Earth Pit 12	0.50	0.30			
Earth Pit 13	0.62	0.30			
Earth Pit 14	0.46	0.73			
Earth Pit 15	0.68	0.40			
Earth Pit 16	0.66	0.39			
Earth Pit 17	0.64	0.21			
Earth Pit 18	0.58	0.60			
Earth Pit 19	0.71	0.55			
Earth Pit 20	0.53	0.28			
Earth Pit 21	0.45	0.75			
Earth Pit 22	0.51	0.57			
Earth Pit 23	0.64	0.29			
Earth Pit 24	0.72	0.71			
Earth Pit 25	0.45	0.57			
Earth Pit 26	0.31	0.32			
Earth Pit 27	0.49	0.23			
Earth Pit 28	0.70	0.19			
Earth Pit 29	0.36	0.32			
Earth Pit 30	0.55	0.34			
Earth Pit 31	0,60	0.33			
Earth Pit 32	0.67	0.41			
Earth Pit 33	0.55	0.31			





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

## WORK COMPLETION REPORT

**Page:** 8 of 15

Earth Pit 34	0.67	0.33
Earth Pit 35	0.64	0.46
Earth Pit 36	0.49	0.34
Earth Pit 37	0.56	0.34
Earth Pit 38	0.62	0.34
Earth Pit 39	0.47	0.35
Earth Pit 40	0.62	0.40
Earth Pit 41	0.51	0.11
Earth Pit 42	0.58	0.11
Earth Pit 43	0.63	0.66
Earth Pit 44	0.51	0.61
Earth Pit 45	0.47	0.46
Earth Pit 46	0.55	0.47
Earth Pit 47	0.67	0.46
Earth Pit 48	0.64	0.46
Earth Pit 49	0.49	0.57
Earth Pit 50	0.62	0.56
Earth Pit 51	0.71	0.43
Earth Pit 52	0.66	0.50
Earth Pit 53	0.66	0.47
Earth Pit 54	0.45	0.37
Earth Pit 55	0.54	0.42
Earth Pit 56	0.68	0.20
Earth Pit 57	0.53	0.53
Earth Pit 58	0.69	0.53
Earth Pit 59	0.46	0.25
Earth Pit 60	0.71	0.50





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 9 of 15

# 5 PICTURES



Fig 5.1: Excavation and cable laying



Fig 5.2: Earth mat installed



Fig 5.3: Copper cables connected to earth rod



Fig 5.4: Earth rod in ground





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 10 of 15



Fig 5.5: Termination of lighting pole to earth



Fig 5.6: Earth chambers



Fig 5.7: Earth rod installation process



Fig 5.8: Driving down earth rod





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 11 of 15



Fig 5.9: Earthing enhancement chemical



Fig 5.10: Cable laying on road crossing




Fig 5.11: Bonding of earth grid with c-clamp



Fig 5.12: Cable bonding ongoing





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 12 of 15



Fig 5.13: Site restoration



Fig 5.14: Earth chamber numbering



Fig 5.15: Test probe on copper rod



Fig 5.16: Test result for earth pit 15





Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 13 of 15



Fig 5.17: Test result for earth pit 37



Fig 5.18: Testing result



Fig 5.19: Testing team



Fig 5.20: Testing team





Contract No:

LEKOIL

Rev: A1

Document Title:

WORK COMPLETION REPORT

Page: 14 of 15

#### COMPLETION STATEMENT

This Project has been tested and confirmed to be sufficient for the purpose it was designed for. We hereby report this project as commissioned.

06/09/22

Engr. Igbinosa Moses

**Electrical Project Engineer** 

ACEBEACON GLOBAL ENERGY LIMITED

Sign
Name: Harrison Brasmus

Designation: ASSIST Elect

GREEN ENERGY INTERNATIONAL LIMITED

Sign Vitus Ugum ation: Proj. Engr.

Designation:

**LEKOIL NIGERIA LIMITED** 





Contract No:




Rev: A1

WORK COMPLETION REPORT

**Page:** 15 of 15

# 7 APPENDIX

# 7.1 As-Built Layout Drawings



#### NOTE:

- 1: CLOUDED AREA DENOTES MODIFICATIONS MADE DUE TO EXISTING PERMANENT OBSTRUCTIONS SUCH AS ROADS AND OTHER STRUCTURES
- 2: ALL MODIFICATIONS WERE APPROVED BY SITE PROJECT ENGINEER





Contract No:

LEKOIL

Rev: A1

Document Title: WORK COMPLETION REPORT

**Page:** 1 of 35

## 1 OVERALL PROJECT COMPLETION STATEMENT

- I, Engr. Anikpo Chukwuka, Managing Director Acebeacon Global Energy Limited, hereby certifies that:
- 1. All works has been performed in accordance with the scope of work and terms of the contract.
- 2. All minor modifications and field adjustments were duly approved by the site checker.
- 3. As-built drawings has been completed and attached to the appropriate project reports.
- 4. Site has been restored to its previous state after completion of work.
- 5. All remaining materials have been handed over to JV.
- 6. All labourers have been paid in full for all works done.

Afgra

Engr. Anikpo Chukwuka,

Wednesday, 07 September 2022,





Contract No:

**LEKOIL** 

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 2 of 35

# 2 COMPLETED PROJECT S-CURVE

5-26-2022	6-2-2022	6-9-2022	6-16-2022	6-23-2022	6-30-2022	7-7-2022	7-14-2022	8-25-2022	9-1-2022	9-8-2022
Week 1	Week 2	Week 3	Week 4	Week 5	Week 6	Week 7	Week 8	Week 9	Week 10	Week 11
3%	11%	11%	11%	11%	11%	11%	1%	10%	10%	10%
2%	9%	5%	11%	11%	12%	10%	10%	4%	11%	15%
3%	14%	25%	36%	47%	58%	69%	70%	80%	90%	100%
2%	11%	16%	27%	38%	50%	60%	70%	74%	85%	100%
	Week 1 3% 2% 3%	Week 1         Week 2           3%         11%           2%         9%           3%         14%	Week 1         Week 2         Week 3           3%         11%         11%           2%         9%         5%           3%         14%         25%	Week 1         Week 2         Week 3         Week 4           3%         11%         11%         11%           2%         9%         5%         11%           3%         14%         25%         36%	Week 1         Week 2         Week 3         Week 4         Week 5           3%         11%         11%         11%         11%           2%         9%         5%         11%         11%           3%         14%         25%         36%         47%	Week 1         Week 2         Week 3         Week 4         Week 5         Week 6           3%         11%         11%         11%         11%         11%           2%         9%         5%         11%         11%         12%           3%         14%         25%         36%         47%         58%	Week 1         Week 2         Week 3         Week 4         Week 5         Week 6         Week 7           3%         11%         11%         11%         11%         11%         11%           2%         9%         5%         11%         11%         12%         10%           3%         14%         25%         36%         47%         58%         69%	Week 1         Week 2         Week 3         Week 4         Week 5         Week 6         Week 7         Week 8           3%         11%         11%         11%         11%         11%         11%         10%           2%         9%         5%         11%         11%         12%         10%         10%           3%         14%         25%         36%         47%         58%         69%         70%	Week 1         Week 2         Week 3         Week 4         Week 5         Week 6         Week 7         Week 8         Week 9           3%         11%         11%         11%         11%         11%         11%         10%           2%         9%         5%         11%         11%         12%         10%         10%         4%           3%         14%         25%         36%         47%         58%         69%         70%         80%	Week 1         Week 2         Week 3         Week 4         Week 5         Week 6         Week 7         Week 8         Week 9         Week 10           3%         11%         11%         11%         11%         11%         11%         10%         10%           2%         9%         5%         11%         11%         12%         10%         10%         4%         11%           3%         14%         25%         36%         47%         58%         69%         70%         80%         90%







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 3 of 35

# 3 PROJECT PHOTO GALLERY

# 3.1 Solar/Main Perimeter Lighting







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 4 of 35







Contract No:

**LEKOIL** 

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT















Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 6 of 35

















Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 7 of 35













Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 8 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT















Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 10 of 35













Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 11 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT









Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 13 of 35













Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 14 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 15 of 35













Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT















Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

















Contract No:


LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 18 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 19 of 35

# 3.2 Lightning Protection System







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 20 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 21 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 22 of 35













Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 23 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 24 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 25 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 26 of 35







Contract No:


LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT















Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 28 of 35

# 3.3 Earthing Protection System







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 29 of 35







Contract No:


**LEKOIL** 

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 30 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 31 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 32 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 33 of 35













Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

**Page:** 34 of 35







Contract No:

LEKOIL

Rev: A1

**Document Title:** 

WORK COMPLETION REPORT

Page: 35 of 35

